

Drill Log: **NSH-021C**

GeoLogged By:
aolson

GeoLogged By 2:

TechLogged By:
Guillermo

2 of 19

[illegible]

Drill Log: NSH-021C

GeoLogged By:
aolson

GeoLogged By 2:

TechLogged By:
Guillermo

3 of 19

[illegible]

Drill Log: NSH-021C

Drill Started: 1/10/2015
Drill Completed: 1/13/2015
Core Size (ft): UNKNOWN(100)
Contractor: National EWP, Inc
Pre-Collar Contractor : NEWP

GeoLogged By:
aolson

GeoLogged By 2:

TechLogged By:
Guillermo

4 of 19

[illegible]

Drill Log: NSH-021C

GeoLogged By:
aolson

GeoLogged By 2:

TechLogged By:
Guillermo

5 of 19

[illegible]

Drill Log: NSH-021C

GeoLogged By:
aolson

GeoLogged By 2:

TechLogged By:
Guillermo

6 of 19

[illegible]

Drill Log: NSH-021C

Drill Started: 1/10/2015
Drill Completed: 1/13/2015
Core Size (ft): UNKNOWN(100)
Contractor: National EWP, Inc
Pre-Collar Contractor : NEWP

GeoLogged By:
aolson

GeoLogged By 2:

TechLogged By:
Guillermo

7 of 19

[illegible]

Drill Log: NSH-021C

Drill Started: 1/10/2015
Drill Completed: 1/13/2015
Core Size (ft): UNKNOWN(100)
Contractor: National EWP, Inc.
Pre-Collar Contractor : NEWP

GeoLogged By:
aolson

GeoLogged By 2:

TechLogged By:
Guillermo

Comments: Originally NSH-021 but the wrong surface casing was used (13" instead of 14" so the hole was moved and NSH-021B was drilled. NSH-021B was abandoned due to a broken bit in the borehole. The hole was moved and NSH-021C was drilled.

8 of 19

[illegible]

Drill Log: NSH-021C

Drill Started: 1/10/2015
Drill Completed: 1/13/2015
Core Size (ft): UNKNOWN(100)
Contractor: National EWP, Inc.
Pre-Collar Contractor : NEWP

GeoLogged By:
aolson

GeoLogged By 2:

TechLogged By:
Guillermo

9 of 19

[illegible]

Drill Log: NSH-021C

Drill Started: 1/10/2015
Drill Completed: 1/13/2015
Core Size (ft): UNKNOWN(100)
Contractor: National EWP, Inc.
Pre-Collar Contractor : NEWP

GeoLogged By:
aolson

GeoLogged By 2:

TechLogged By:
Guillermo

10 of 19

[illegible]

Drill Log: NSH-021C

Drill Started: 1/10/2015
Drill Completed: 1/13/2015
Core Size (ft): UNKNOWN(100)
Contractor: National EWP, Inc.
Pre-Collar Contractor : NEWP

GeoLogged By:
aolson

GeoLogged By 2:

TechLogged By:
Guillermo

Comments: Originally NSH-021 but the wrong surface casing was used (13" instead of 14" so the hole was moved and NSH-021B was drilled. NSH-021B was abandoned due to a broken bit in the borehole. The hole was moved and NSH-021C was drilled.

11 of 19

[illegible]

Drill Log: NSH-021C

Drill Started: 1/10/2015
Drill Completed: 1/13/2015
Core Size (ft): UNKNOWN(100)
Contractor: National EWP, Inc.
Pre-Collar Contractor : NEWP

GeoLogged By:
aolson

GeoLogged By 2:

TechLogged By:
Guillermo

12 of 19

[illegible]

Drill Log: NSH-021C

Drill Started: 1/10/2015
Drill Completed: 1/13/2015
Core Size (ft): UNKNOWN(100)
Contractor: National EWP, Inc.
Pre-Collar Contractor : NEWP

GeoLogged By:
aolson

GeoLogged By 2:

TechLogged By:
Guillermo

Comments: Originally NSH-021 but the wrong surface casing was used (13" instead of 14" so the hole was moved and NSH-021B was drilled. NSH-021B was abandoned due to a broken bit in the borehole. The hole was moved and NSH-021C was drilled.

13 of 19

[illegible]

Drill Log: NSH-021C

Drill Started: 1/10/2015
Drill Completed: 1/13/2015
Core Size (ft): UNKNOWN(100)
Contractor: National EWP, Inc
Pre-Collar Contractor : NEWP

GeoLogged By:
aolson

GeoLogged By 2:

TechLogged By:
Guillermo

14 of 19

[illegible]

Drill Log: **NSH-021C**

GeoLogged By:
aolson

GeoLogged By 2:

TechLogged By:
Guillermo

15 of 19

[illegible]

Drill Log: NSH-021C

Drill Started: 1/10/2015
Drill Completed: 1/13/2015
Core Size (ft): UNKNOWN(100)
Contractor: National EWP, Inc
Pre-Collar Contractor : NEWP

GeoLogged By:
aolson

GeoLogged By 2:

TechLogged By:
Guillermo

16 of 19

[illegible]

Drill Log: NSH-021C

Drill Started: 1/10/2015
Drill Completed: 1/13/2015
Core Size (ft): UNKNOWN(100)
Contractor: National EWP, Inc.
Pre-Collar Contractor : NEWP

GeoLogged By:
aolson

GeoLogged By 2:

TechLogged By:
Guillermo

Comments: Originally NSH-021 but the wrong surface casing was used (13" instead of 14" so the hole was moved and NSH-021B was drilled. NSH-021B was abandoned due to a broken bit in the borehole. The hole was moved and NSH-021C was drilled.

17 of 19

[illegible]

Drill Log: NSH-021C

Drill Started: 1/10/2015
Drill Completed: 1/13/2015
Core Size (ft): UNKNOWN(100)
Contractor: National EWP, Inc
Pre-Collar Contractor : NEWP

GeoLogged By:
aolson

GeoLogged By 2:

TechLogged By:
Guillermo

18 of 19

[illegible]

Drill Log: NSH-021C

Drill Started: 1/10/2015
Drill Completed: 1/13/2015
Core Size (ft): UNKNOWN(100)
Contractor: National EWP, Inc
Pre-Collar Contractor : NEWP

GeoLogged By:
aolson

GeoLogged By 2:

TechLogged By:
Guillermo

19 of 19

[illegible]